How to **Clean a Sign**

The maintenance and care of a painted or clear coated polyurethane surface would utilize the basic commercially available non-abrasive cleaners and polishes recommended for finishes exposed to the environment.

It is recommended to wait at least 30 days after painting before any cleaning or polishing is attempted. A mild detergent and water solution with soft cloth toweling is often sufficient to remove most dirt followed with a thorough clean water rinse. Application of polish (liquid or paste) should be done with a wet soft cloth covered sponge and buffed with a soft flannel cloth. This is best accomplished in the cooler hours of the day avoiding direct sunlight if possible. Use of polish over satin finishes may result in an increase to the gloss level.

If there are further questions regarding how to clean signs made using Novacryl®, pelase contact info@novaolymers.com



Nova Polymers, Inc. info@novapolymers.com www.novapolymers.com 1-888-484-6682

Additives

Training





mpc PAINT DROPS DESIGN in color is a trademark of PPG Industries Ohio, Inc. mpc MATTHEWS PAINT and Droplet and Rounded Rectangle is a registered trademark of PPG Industries Ohio, Inc.



Learn More:

760 Pittsburgh Drive • Delaware, OH 43015 Toll Free: 800.323.6593 • Fax: 800.947.0377 www.matthewspaint.com

